

© PAJ / JPO

PN - JP11013640 A 19990119

TI - OIL PUMP STRUCTURE

AB - PROBLEM TO BE SOLVED: To decrease the generation of a moment due to offset in the axial direction of a contact point between the internal part rotary member of an oil pump and the rotation drive member thereof and improve durability of an internal rotation member and a bush for the internal rotation member.

- SOLUTION: An oil pump structure is formed such that a protrusion part 2a formed in the peripheral symmetrical position of the sleeve 2 of the torque converter is inserted in a key groove formed in the peripheral direction-symmetrical position of the inner rotor of an oil pump. In this case, a circular arc is formed in the two end faces in the rotation direction of the protrusion part 2a of the sleeve 2 and offset in the axial direction of a contact point between two members occurring during decentering of the central axes of an inner rotor and the sleeve.

I - F04C2/10


PA - NISSAN MOTOR CO LTD



IN - KOYAMA TAKAO


ABD - 19990430

ABV - 199904


AP - JP19970162420 19970619










(a)




(b)











(a)



(b)



(a)

↓ 吐出圧(入力一定)

インナーギア

インナーギアブッシュ

ステータシフト

クリアランス

$P$  (クサビ圧)

$F_1$

(b)

↓ 吐出圧(入力一定)

インナーギア


インナーギアブッシュ

ステータシ


クリアランス

$P$  (クサビ圧)

$F_2$




(b) 11-1




(c) 11-2



(d)





**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**